



TA M



art.	descrizione	øv	Lt	øf	P	M	pz
90245	TA M6	M 6	49.5	10	65	5	50
90246	TA M8	M 8	56.5	12	70	12	50
90247	TA M10	M 10	69.0	15	90	20	25
90248	TA M12	M 12	85.5	18	115	35	25

$L_v = L_t + S$