




Serratura comando maniglia I92 con 4 funghi F16

Disegni tecnici



prolungabile	argento												
		92	28	8	1.050	4	1.950 - 2.200	16	2.200	5	232010		
			35	8	1.050	4	1.950 - 2.200	16	2.200	5	232011		
			40	8	1.050	4	1.950 - 2.200	16	2.200	5	232012		
			45	8	1.050	4	1.950 - 2.200	16	2.200	5	232013		
			50	8	1.050	4	1.950 - 2.200	16	2.200	5	232014		
			55	8	1.050	4	1.950 - 2.200	16	2.200	5	232015		
			65	8	1.050	4	1.950 - 2.200	16	2.200	5	232017		


Tabella posizionamento viti

N°														
232010	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232011	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232012	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232013	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232014	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232015	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100
232017	13	-1.000	-874	-806	-529	-461	-168	129,5	341	409	759,5	824,5	970	1.100



Serratura comando maniglia I92 con 4 funghi F16

Tabella punti di chiusura

N°		Z1	Z2	Z3	Z4	
232010	4	-840	-495	375	795	
232011	4	-840	-495	375	795	
232012	4	-840	-495	375	795	
232013	4	-840	-495	375	795	
232014	4	-840	-495	375	795	
232015	4	-840	-495	375	795	
232017	4	-840	-495	375	795	